
10
30
30
40
40
Scanner
Scanner
PACS Workstation
PACS Workstation
22
PACS Server
20
PACS Workstation
40
Scanner
30

FIG. 1


10
30
35
20
Scanner
A/D Converter
PACS
Server
PACS Workstation
Display
40
45

FIG. 2